

## Domain Reject

If a packet is followed by a return from the system board of this type, the data in the packet that generated this reject was invalid. Possible causes include an invalid message type, subpacket data outside of spec, a subpacket length that is incorrect, or other malformities.

11 byte Header

Message Type = 0x86

Timestamp should equal the timestamp in the packet that generated the ACK.